

CASE REPORT

Inadvertent malposition of a permanent ventricular lead into the middle cardiac vein was misdiagnosed as lead perforation

Mingxian Chen MD | Zhihong Wu MD  | Zhenjiang Liu MD | Lin Hu MD |
Xuping Li MD | Qiming Liu MD | Shenghua Zhou MD

Department of Cardiology, The Second Xiangya Hospital of Central South University, Changsha, China

Correspondence

Zhihong Wu, Department of Cardiology, The Second Xiangya Hospital of Central South University, middle Ren-Min road No.139, 410011 Changsha, Hunan, China. Email: wuzhihong915@csu.edu.cn

Funding information

The authors would like to thank LY, Minjia Xiao, and Zhuo Wang for modification. Financial support was obtained from the National Natural Science Foundation of China No.81800302 and Provincial Natural Science Foundation of Hunan No. 2019JJ50871

Abstract

A 54-year-old man had a dual-chamber pacemaker implantation 9 years ago because of sick sinus syndrome at a different facility. The patient did not undergo any evaluation of his pacemaker for a long time with cardiologist. The patient was admitted to another hospital manifesting dyspnea and palpitation with atrial fibrillation for 1 month, and he was diagnosed with ventricular lead perforation. For further treatment, he was referred to our hospital, and an elective replacement indicator (ERI) of the battery state and a malpositioned ventricular lead into the middle cardiac vein were found. Finally, the pacing lead was left in the primary place and the pacemaker was replaced.

KEYWORDS

malposition, middle cardiac vein, pacemaker, pacing lead

1 | INTRODUCTION

Malposition of a right ventricular lead into the coronary vein is an uncommon complication. Although its actual incidence still remains unclear, an increased proportion has been reported because of the rising number of pacemaker implantation (Wynn et al., 2013). During the procedure, the inadvertent implantation of the right ventricular lead into the middle cardiac vein (MCV) may be easily ignored due to the MCV anatomic course resembling an RV apical position under fluoroscopic guidance, and then, it could be easily misdiagnosed as ventricular lead perforation. Herein, we report a case who was misdiagnosed with ventricular lead perforation at a local hospital, but it was found that the lead was inadvertently implanted into middle cardiac vein. To avoid this complication, we discuss several noninvasive methods used to place the lead in correct position during pacemaker implantation (Villanueva et al., 1987).

2 | CASE PRESENTATION

A 54-year-old male patient was admitted to another center with palpitation and dyspnea because of the onset of atrial fibrillation 1 month ago. The patient had a history of dual-chamber pacemaker implantation for sick sinus syndrome 9 years ago. It was learned that the patient did not undergo any evaluation of his pacemaker for a long time. On admission to the cardiovascular department, it was found that the ventricular lead was located at left ventricular side on chest X-ray. The 12-lead ECG presented atrial fibrillation with heart rate of 81 bpm and normal ventricular pacing spikes followed by QRS pattern of complete right bundle branch block (Figure 1). According to the ECG and chest radiograph, the patient was diagnosed as chronic perforation of ventricular pacing lead. Two-dimensional echocardiograms confirmed that the ventricular pacing lead was imaged in the right atrium but not in right ventricular chamber or across the tricuspid valve. Magnet response was evaluated to check for

This is an open access article under the terms of the [Creative Commons Attribution-NonCommercial-NoDerivs](https://creativecommons.org/licenses/by-nc-nd/4.0/) License, which permits use and distribution in any medium, provided the original work is properly cited, the use is non-commercial and no modifications or adaptations are made.

© 2022 The Authors. *Annals of Noninvasive Electrocardiology* published by Wiley Periodicals LLC.




FIGURE 1 A 12-lead ECG presents atrial fibrillation with a heart rate of 81 bpm and several premature ventricular contractions. Normal ventricular chamber pacing with pacemaker spikes. ECG recorded at 25 mm/sec




FIGURE 2 Chest roentgenogram of this patient showing contour of electrode leads in posteroanterior. The tip of ventricular lead looks like locating at apex

possible battery depletion. SSS was observed by placing the magnet, whereas wide QRS recurred when the magnet was removed from over the pacemaker. The dual-chamber pacemaker was recorded with normal pacing and sensing parameters of right atrium and ventricle lead. Fluoroscopy was used to monitor the lead position at

posteroanterior and left/right anterior oblique view (Figures 2-4), which showed that the tip of ventricular lead looked like locating inside the pericardial cavity. After clinical evaluation, it was considered that the ventricular pacing lead was located in middle cardiac vein. Because of the normal parameters of the ventricular lead, we decided to replace the pacemaker and retain the pacing lead. Then, the patient was taken to the catheter laboratory for pacemaker replacement. The patient was discharged on the next day and did not have any problem during the follow-up.

3 | DISCUSSION

The coronary sinus is a wide venous channel situated in the posterior part of the atrioventricular groove. It has five major tributaries. The middle cardiac vein runs along the posterior inter-ventricular groove receiving blood from both ventricles. It usually opens into the coronary sinus close to the ostium (Shettigar et al., 1989). During the procedure, it may be easily ignored the inadvertent implantation of the right ventricular lead into the MCV due to the MCV anatomic course resembling an RV apical position under fluoroscopic guidance. There are several noninvasive methods provided for avoiding malposition. During the implantation, firstly, the ventricular lead was delivered into the right ventricular outflow tract, and subsequently, premature ventricular contractions were observed in V₁ with a QS/rS pattern. Additionally, if the ECG monitoring presents a pattern of right bundle branch block during ventricular pacing on lead V₁, an echocardiographic assessment




FIGURE 3 Chest roentgenogram of this patient showing contour of electrode leads in left anterior oblique view. The tip of ventricular lead looks like locating inside the pericardial cavity




FIGURE 4 Chest roentgenogram of this patient showing contour of electrode leads in right anterior oblique view. The tip of ventricular lead looks like locating inside the pericardial cavity

should be performed to evaluate the lead placement. In normal position of right ventricular pacing lead according to two-dimensional echocardiograms, the pacing lead passes through the right atrium and can be traced across the tricuspid valve and into the right ventricular. However, if the right ventricular pacing lead is in a malposition, it was not imaged across the tricuspid valve and ventricular chamber (Topaloglu et al., 2015; Zaher et al., 2011). Furthermore, the proper position of the right ventricular pacing

lead is at right ventricular median septum. On the left oblique view, the tip of the ventricular lead should be located toward the left of spine (Paravolidakis et al., 2004).

4 | CONCLUSION

Although inadvertent malposition of right ventricular pacing lead into middle cardiac vein may be rarely observed, it should be avoided according to several noninvasive methods.

CONFLICT OF INTEREST

We declare that we have no financial and personal relationships with other people or organizations that can inappropriately influence our work.

INFORMED CONSENT

Written informed consent was obtained from this patient.

ETHICAL APPROVAL

We identify that the ethics committee of The Second Xiangya Hospital of Central South University have approved the case, and that this case conforms to recognized standards, Declaration of Helsinki.

AUTHORS CONTRIBUTIONS

Mingxian Chen contributed significantly to data collection and manuscript preparation. Xuping Li contributed to the conception of the study. Zhenjiang Liu and Lin Hu performed the patient management. Zhihong Wu and Qiming Liu performed the pacemaker implantation. Shenghua Zhou and Zhihong Wu performed the analysis with constructive discussions. All authors agree on the order in which their names will be listed in the manuscript.

DATA AVAILABILITY STATEMENT

It is a case report. No data.

ORCID

Zhihong Wu  <https://orcid.org/0000-0002-6148-3849>

REFERENCES

- Paravolidakis, K. E., Hamodraka, E. S., Kolettis, T. M., Psychari, S. N., & Apostolou, T. S. (2004). Management of inadvertent left ventricular permanent pacing. *Journal of Interventional Cardiac Electrophysiology*, 10, 237–240. <https://doi.org/10.1023/B:JICE.0000026918.50374.0d>
- Shettigar, U. R., Loungani, R. R., & Smith, C. A. (1989). Inadvertent permanent ventricular pacing from the coronary vein: An electrocardiographic, roentgenographic, and echocardiographic assessment. *Clinical Cardiology*, 12, 267–274. <https://doi.org/10.1002/clc.4960120508>
- Topaloglu, S., Bayraktar, F., Okten, S., Cetin, S., Ozeke, O., Cay, S., & Aras, D. (2015). Inadvertent placement of pacemaker lead into the middle cardiac vein. Inadvertent placement of pacemaker lead into the middle cardiac vein. *Herz*, 40, 734–737. <https://doi.org/10.1007/s00059-014-4134-x>
- Villanueva, F. S., Heinsimer, J. A., Burkman, M. H., Fananapazir, L., Halvorsen, R. A., & Chen, J. T. (1987). Echocardiographic detection

of perforation of the cardiac ventricular septum by a permanent pacemaker lead. *American Journal of Cardiology*, 59, 370–371.

[https://doi.org/10.1016/0002-9149\(87\)90821-6](https://doi.org/10.1016/0002-9149(87)90821-6)

Wynn, G. J., Weston, C., Cooper, R. J., & Somauroo, J. D. (2013). Inadvertent left ventricular pacing through a patent foramen ovale: Identification, management and implications for postpacemaker implantation checks. *BMJ Case Reports*, 2013:bcr2012008312. <https://doi.org/10.1136/bcr-2012-008312>

Zaher, M. F., Azab, B. N., Bogin, M. B., & Bekheit, S. G. (2011). Inadvertent malposition of a permanent pacemaker ventricular lead into the left ventricle which was initially missed and diagnosed two years later: A case report. *Journal of Medical Case Reports*, 5, 54. <https://doi.org/10.1186/1752-1947-5-54>

How to cite this article: Chen, M., Wu, Z., Liu, Z., Hu, L., Li, X., Liu, Q., & Zhou, S. (2022). Inadvertent malposition of a permanent ventricular lead into the middle cardiac vein was misdiagnosed as lead perforation. *Annals of Noninvasive Electrocardiology*, 27, e12949. <https://doi.org/10.1111/anec.12949>