



Case report

Fracture of the neck of an uncemented femoral component unrelated to trunnion corrosion

Jonathan R. Peterson, MD ^{a,*}, Timothy M. Wright, PhD ^b, Samuel S. Wellman, MD ^a, Paul F. Lachiewicz, MD ^a^a Department of Orthopaedic Surgery, Duke University, Durham, NC, USA^b Hospital for Special Surgery, New York, NY, USA

ARTICLE INFO

Article history:

Received 30 October 2018

Received in revised form

29 January 2019

Accepted 31 January 2019

Available online 7 March 2019

Keywords:

Femoral component neck fracture

Total hip arthroplasty

Revision

Catastrophic failure

ABSTRACT

This is the first report, to our knowledge, of a fracture, unrelated to trunnion corrosion, through the midneck of a well-fixed uncemented cobalt-chromium alloy femoral component that had been implanted via a total hip revision arthroplasty 25 years ago. Three years after a second revision for polyethylene wear, the patient noted an acute onset of pain in the left hip. There was no antecedent pain in the hip or thigh. Radiographs and intraoperative findings showed a well-fixed femoral component. Electron microscopic retrieval analysis showed intergranular material cracks. Revision of the femoral component was performed with an extended trochanteric osteotomy. This fracture of the femoral component neck was likely related to metal fabrication techniques, and surveillance of this component may be warranted.

© 2019 The Authors. Published by Elsevier Inc. on behalf of The American Association of Hip and Knee Surgeons. This is an open access article under the CC BY-NC-ND license (<http://creativecommons.org/licenses/by-nc-nd/4.0/>).

Introduction

Fracture of the femoral component of a total hip arthroplasty is a rare cause for revision compared with infection, aseptic loosening, and instability [1,2]. Fracture of both cemented and cementless femoral component stems has been reported [1–4]. In the 1970s, the reported rate of stem fracture ranged from 0.23% to 10.7% [3–5]. These fractures usually occurred in the middle third of the component and were due to fatigue failure related to cantilever bending with insufficient proximal support or fixation [6]. Despite improvements in materials and manufacturing techniques, fracture of modern cemented femoral components has still been reported [6–8], with possible causative factors including obesity, excessive physical activity, and severe trauma [9]. Other patient factors include male sex, tall patients, concurrent lumbar spine pathology, and presence of bilateral hip arthroplasties [3,7,10]. Predisposing surgical factors include varus alignment or an undersized femoral

component, an asymmetric cement mantle, and poor proximal bone support [7,10–12]. Flaws in design, manufacturing defects, and stress risers from postmanufacturing processing have also been associated with femoral component fracture [6,10,13]. Fracture of an uncemented cobalt-chromium alloy stem with small beads (anatomic medullary locking; DePuy International, Leeds, England) was associated with small-diameter stems implanted in revisions and deficiency of the proximal femur [14].

Fracture of the neck of a cemented or uncemented femoral component is an even rarer complication than stem fracture [9,13,15–19]. This complication is distinct from whole trunnion failure or fracture as has been recently reported with certain femoral components and related to severe corrosion [20,21]. This is the first report, to our knowledge, of a patient with a nontraumatic fracture through the neck (distal to the trunnion) of an uncemented, small-bead cobalt-chromium alloy femoral component, occurring 25 years after implantation. Although a case series of stem fractures was reported for this particular femoral component related to loosening [8], the current case is unique. The patient provided informed consent for publication of deidentified medical information regarding this case.

Case history

The patient is a 71-year-old man (weight 94.2 kg, height 185.4 cm, body mass index 27.4) who underwent a left cemented total hip

One or more of the authors of this article have disclosed potential or pertinent conflicts of interest, which may include receipt of payment, either direct or indirect, institutional support, or association with an entity in the biomedical field which may be perceived to have potential conflict of interest with this work. For full disclosure statements refer to <https://doi.org/10.1016/j.artd.2019.01.006>.

* Corresponding author. Duke Orthopaedic Surgery, DUMC Box 3000, Durham, NC 27710, USA. Tel.: +1 919 684 8111.

E-mail address: Jonathan.peterson@duke.edu

<https://doi.org/10.1016/j.artd.2019.01.006>

2352-3441/© 2019 The Authors. Published by Elsevier Inc. on behalf of The American Association of Hip and Knee Surgeons. This is an open access article under the CC BY-NC-ND license (<http://creativecommons.org/licenses/by-nc-nd/4.0/>).

arthroplasty in 1982 for posttraumatic arthritis at another hospital. In 1992, at a different hospital, he had revision of both components for aseptic loosening with uncemented components: a cobalt-chromium alloy with a bead size of #10 C-taper stem (Omnifit; Osteonics, Rutherford, NJ), a +10 cobalt-chromium alloy femoral head, and a 62-mm hemispherical acetabular component with conventional polyethylene. In 2014, he developed mild hip pain, and radiographs showed severe polyethylene wear with osteolysis in the greater trochanter (Fig. 1a and b). At revision at our hospital, both components were well fixed, and liner and head exchange were performed, using a highly cross-linked polyethylene liner and a +10 C-taper low friction ion treatment 32-mm cobalt-chromium alloy femoral head (Stryker, Rutherford, NJ). The intraoperative cultures yielded no growth. No postoperative complications occurred, and the patient resumed full activities at 3 months. The patient was asymptomatic until 4 years later when he presented to the emergency department with an acute onset of pain in the left hip after stepping down off a ladder. He did not fall but heard a loud “crack” with immediate pain and inability to ambulate. Before this episode, he was able to ambulate 2–3 miles per day without a support. The left leg was shortened and externally rotated. Radiographs showed a fracture through the neck of the well-fixed femoral component distal to the trunnion (Fig. 2a and b). C-reactive protein and erythrocyte sedimentation rate were within normal limits.

At revision, no corrosion at the trunnion was observed, and no pseudotumor or abductor muscle necrosis was found. The acetabular component was well fixed and was retained. The femoral component removal required a 10-cm extended trochanteric osteotomy, and a modular tapered fluted stem (Restoration; Stryker) was implanted, with a 32 + 8-mm cobalt-chromium alloy head; the osteotomy was repaired with cables. No postoperative complications occurred. At 3 months postoperatively, the patient had mild thigh pain and was able to ambulate long distances with one crutch. Radiographs showed good fixation and a healed osteotomy (Fig. 3a and b).

Implant analysis

The fractured component was evaluated by one of the authors (T.M.W.) by light and scanning electron microscopy. No notable

corrosion of the trunnion was found, consistent with the intraoperative findings. The surfaces of the fracture of the neck are consistent with fatigue fractures in cobalt-chromium alloy with an intergranular appearance (Fig. 4a). In addition to the crack that formed the main fracture (Fig. 4b), electron microscopy showed a considerable number of intergranular cracks, consistent with intergranular corrosion, as the probable cause for the failure. No accompanying material defects, such as porosity, were noted on the fracture surface.

Discussion

The published reports of fracture of the neck of a femoral component include all 3 of the common orthopedic metallic alloys, with failures attributed to several causes (Table 1). Burstein and Wright first reported the fracture of the neck of a stainless steel, cemented femoral component in 2 patients [15]. These fractures were associated with a design flaw in the trapezoidal shaped neck leading to excessive tensile stress [15]. Rand and Chao [18] reported 2 fractures of the neck and 32 fractures of the stem of the same prosthesis in a case series of 1808 hips. Vatani et al. [13] reported 9 patients with a fracture of the neck of a stainless steel Charnley-type cemented femoral component and concluded that these fractures were associated with the design of an inadequately congruent radius, leading to abnormal force transmission through the neck. Aspenberg et al. [22] reported 5 neck fractures in 25 Brunswik-type cemented components, with failure attributed to a faulty welding procedure. Fractures of the femoral component neck have also been reported with cemented and cementless titanium alloy femoral components. Magnissalis et al. [23] described 2 titanium alloy cemented femoral components (Optifix; Smith and Nephew, Andover, MA) that had fractured at the stem-neck junction. Light and electron microscopy showed striations, with cracks propagating along multiple plateaus, consistent with fatigue. Fatigue fractures of the neck of the femoral component of 3 other titanium alloy stems have been reported: the hydroxyapatite-coated Furlong (JRI Limited, London, UK) [9], the SEM3 type (Science et Médecine, Montrouge, France) [17], and the Accolade I (Stryker, Kalamazoo, MI) [1].




Figure 1. Anteroposterior (a) and lateral (b) radiographs of the left hip before head and liner exchange. Radiographs demonstrate polyethylene wear and osteolysis in the greater trochanter.




Figure 2. Anteroposterior (a) and oblique lateral (b) radiographs of the left hip on the day of injury, with fracture through the neck of the femoral component.

Fractures of the proximal portion of uncemented titanium alloy femoral components with cobalt-chromium alloy femoral heads and highly cross-linked polyethylene have also been reported secondary to mechanically assisted crevice corrosion or trunnionosis of the modular connection between the head and stem. Trunnionosis has been associated with a variety of prodromal symptoms and operative findings of pseudotumor, soft tissue damage, and visible corrosion at the head-neck junction [25–27]. Extreme cases show gross material loss and deformation of the trunnion on the femoral stem, across several designs with variable neck lengths and head sizes, “skirted or non-skirted” femoral heads [20]. One report of fracture of the proximal femoral component with trunnionosis noted corrosion, scoring, and scratches at the site of fracture [21]. There have also been reports of fracture of the neck

of modular or dual-taper titanium alloy femoral components, but these were likely related to mechanically assisted crevice corrosion in mixed metal composites [28,29].

Only fewer reports of fractures of the neck of a cobalt-chromium alloy femoral component exist. Lee and Kim [6] reported that the early fracture of the neck of 2 cemented cobalt-chromium components (Opteon; Exactech, Gainesville, FL) was associated with a stress riser at the site of laser etching. Other reports noted corrosion at the site of fracture. Gilbert et al. [16,30] reported 2 uncemented prostheses (PCA; Howmedica, Rutherford, NJ) with fracture of the neck, intragranular corrosion and deep penetration into the microstructure, increased porosity at the grain boundaries, and cyclic fatigue loading of the neck. Lam et al. [24] reported 4 cases of fracture of the neck, directly adjacent to the femoral head, in




Figure 3. Anteroposterior (a) and lateral (b) radiographs of the left hip at 3 months postoperatively. Radiographs demonstrate healing of the osteotomy site and stable positioning of the components.




Figure 4. Macroscopic photograph (a) of the fractured implant demonstrating typical fracture between the grains of the Co-Cr casting that resembles a series of up and down pyramids. Electron microscopy image (b) demonstrating additional intergranular cracks besides the one that formed the main fracture (arrow heads). Co-Cr, cobalt-chromium.

uncemented femoral components (Omnifit; Osteonics, Allandale, NJ). Retrieval analysis showed corrosion, and 3 of the 4 hips had a “skirted” modular head that may have contributed to impingement and corrosion. Morley et al. [10] reported a fracture of the neck of a cemented femoral component (C-STEM; DePuy, Warsaw, IN) in a metal-on-metal hip and hypothesized that increased fretting of the large femoral head on a stem with a small-diameter taper contributed to corrosion and the eventual fracture.

This case report is distinct from the other cases of fracture of the neck of a cobalt-chromium alloy femoral component because this component was uncemented, with a 32-mm metal femoral head on a polyethylene liner, and the fracture occurred in the midneck region. No evidence of corrosion secondary to fretting of the trunnion was evident on microscopic analysis. The femoral component had a well-fixed, small bead ingrowth surface and was without apparent material defects or mechanical damage. The patient was not obese, did not participate in high-impact activities, and had no other risk factors for femoral component fracture [3,7,10,12]. Furthermore, the fracture was unrelated to mechanically assisted crevice corrosion because the patient was asymptomatic before the sudden, atraumatic fracture of the neck and no pseudotumor or soft tissue damage was found intraoperatively. Gilbert and colleagues [16] also reported on neck fractures in 2 modular hip implants with cobalt-chromium alloy heads and stems, but in both those cases, the intergranular porosity, caused by improper manufacturing, contributed directly to the fractures. Lee and Kim [6], in their report of 2 neck fractures in cobalt-chromium alloy head and stem femoral

components, attributed the fatigue fractures to stress concentrations caused by local metallurgical alterations in the region around the laser-etched markings on the neck. We found no such evidence of manufacturing or etching problems in the fractured component from our case. We suggest that this case represents a type of fatigue failure. The long neck length (+10) and longevity of the implant (25 years) likely contributed to cantilever bending forces, resulting in failure at the midpoint of the neck between the center of rotation and the fixed portion of the stem. However, it was not associated with loosening or mechanically assisted crevice corrosion. This rare instance of neck fracture has not yet been reported to MedWatch, the FDA’s Safety Information and Adverse Reporting Program. Our institution does not require reporting; however, submission of device failures to centralized databases is important.

Summary

Fracture of the neck of a femoral component is a rare complication after total hip arthroplasty with cemented and, less commonly, uncemented components and is usually associated with design or material defects or trunnion corrosion. Although this cobalt-chromium alloy femoral component design, when cemented, has been reported to cause fracture in the midstem after proximal loosening, this is the first report of a fracture of the neck of a well-fixed uncemented femoral component not related to trunnion corrosion.

Table 1
Reports of fractures of the neck of femoral components.

Authors	Year	Fixation	Material	Component name (manufacturer)	No. of cases	Presumed etiology
Burstein and Wright [15]	1985	Cement	Stainless steel	Trapezoidal-28 (Zimmer)	2	Design flaw
Rand and Chao [18]	1987	Cement	Stainless steel	Trapezoidal-28 (Zimmer)	2	Design flaw
Aspenberg et al [22]	1987	Cement	Stainless steel	Brunswik (Mecron GmbH)	5	Welding process
Vatani et al [13]	2002	Cement	Stainless steel	Charnley type (MedTec Brazil)	9	Design flaw
Magnisallis et al [23]	2003	Cement	Titanium alloy	Optifix (Smith and Nephew)	2	Fatigue failure at the area of porous coating
Morgan-Hough et al [9]	2004	Cementless	Titanium alloy	Furlong (JRI Limited)	1	Fatigue
Grivas et al [17]	2007	Cementless	Titanium alloy	SEM3 type (Science et Médecine)	1	Fatigue, patient with strenuous manual labor occupation
Spayner et al [1]	2016	Cementless	Titanium alloy	Accolade I (Stryker)	3	Unknown (retrieval analysis not performed)
Lee and Kim [6]	2001	Cement	Co-Cr alloy	Opteon (Exactech)	2	Laser etching stress riser
Gilbert et al [16]	1994	Cementless	Co-Cr alloy	PCA (Howmedica)	2	Corrosion
Lam et al [24]	2008	Cementless	Co-Cr alloy	Omnifit (Osteonics)	4	Crevices and intergranular corrosion
Morley et al [10]	2012	Cemented	Co-Cr alloy	C-STEM (DePuy)	1	Corrosion in large head metal-on-metal hip
Present case	2018	Cementless	Co-Cr alloy	Omnifit (Osteonics)	1	Casting process

Co-Cr, cobalt-chromium.

References

- [1] Spanyer J, Hines J, Beaumont CM, Yerasimides J. Catastrophic femoral neck failure after THA with the accolade((R)) I stem in three patients. *Clin Orthop Relat Res* 2016;474:1333.
- [2] Bozic KJ, Kurtz SM, Lau E, et al. The epidemiology of revision total hip arthroplasty in the United States. *J Bone Joint Surg Am* 2009;91:128.
- [3] Charnley J. Fracture of femoral prostheses in total hip replacement. A clinical study. *Clin Orthop Relat Res* 1975;111:105.
- [4] Heck DA, Partridge CM, Reuben JD, et al. Prosthetic component failures in hip arthroplasty surgery. *J Arthroplasty* 1995;10:575.
- [5] Martens M, Aernoudt E, de Meester P, et al. Factors in the mechanical failure of the femoral component in total hip prosthesis. Report of six fatigue fractures of the femoral stem and results of experimental loading tests. *Acta Orthop Scand* 1974;45:693.
- [6] Lee EW, Kim HT. Early fatigue failures of cemented, forged, cobalt-chromium femoral stems at the neck-shoulder junction. *J Arthroplasty* 2001;16:236.
- [7] Galante JO. Causes of fractures of the femoral component in total hip replacement. *J Bone Joint Surg Am* 1980;62:670.
- [8] Della Valle AG, Becksac B, Anderson J, et al. Late fatigue fracture of a modern cemented [corrected] cobalt chrome stem for total hip arthroplasty: a report of 10 cases. *J Arthroplasty* 2005;20:1084.
- [9] Morgan-Hough CV, Tavakkolizadeh A, Purkayastha S. Fatigue failure of the femoral component of a cementless total hip arthroplasty. *J Arthroplasty* 2004;19:658.
- [10] Morley D, Starks I, Lim J. A case of a C-stem fracture at the head-neck junction and a review of the literature. *Case Rep Orthop* 2012;2012:158604.
- [11] Ritter MA, Campbell ED. An evaluation of Trapezoidal-28 femoral stem fractures. *Clin Orthop Relat Res* 1986;212:237.
- [12] Carlsson AS, Gentz CF, Stenport J. Fracture of the femoral prosthesis in total hip replacement according to Charnley. *Acta Orthop Scand* 1977;48:650.
- [13] Vatani N, Comando D, Acuna J, Prieto D, Caviglia H. Faulty design increases the risk of neck fracture in a hip prosthesis. *Acta Orthop Scand* 2002;73:513.
- [14] Unnanuntana A, Chen DX, Unnanuntana A, Wright TM. Trunnion fracture of the anatomic medullary locking a plus femoral component. *J Arthroplasty* 2011;26:504.e13-6.
- [15] Burstein AH, Wright TM. Neck fractures of femoral prostheses. A report of two cases. *J Bone Joint Surg Am* 1985;67:497.
- [16] Gilbert JL, Buckley CA, Jacobs JJ, Bertin KC, Zernich MR. Intergranular corrosion-fatigue failure of cobalt-alloy femoral stems. A failure analysis of two implants. *J Bone Joint Surg Am* 1994;76:110.
- [17] Grivas TB, Savvidou OD, Psarakis SA, et al. Neck fracture of a cementless forged titanium alloy femoral stem following total hip arthroplasty: a case report and review of the literature. *J Med Case Rep* 2007;1:174.
- [18] Rand JA, Chao EY. Femoral implant neck fracture following total hip arthroplasty. A report of three cases. *Clin Orthop Relat Res* 1987;221:255.
- [19] Allcock S, Ali MA. Early failure of a carbon-fiber composite femoral component. *J Arthroplasty* 1997;12:356.
- [20] Banerjee S, Cherian JJ, Bono JV, et al. Gross trunnion failure after primary total hip arthroplasty. *J Arthroplasty* 2015;30:641.
- [21] Botti TP, Gent J, Martell JM, Manning DW. Trunion fracture of a fully porous-coated femoral stem. *Case Report. J Arthroplasty* 2005;20:943.
- [22] Aspenberg P, Kolmert L, Persson L, Onnerfalt R. Fracture of hip prostheses due to inadequate welding. *Acta Orthop Scand* 1987;58:479.
- [23] Magnissalis EA, Zinelis S, Karachalios T, Hartofilakidis G. Failure analysis of two Ti-alloy total hip arthroplasty femoral stems fractured in vivo. *J Biomed Mater Res B Appl Biomater* 2003;66:299.
- [24] Lam LO, Stoffel K, Kop A, Swarts E. Catastrophic failure of 4 cobalt-alloy Omnifit hip arthroplasty femoral components. *Acta Orthop* 2008;79:18.
- [25] Cooper HJ, Della Valle CJ, Berger RA, et al. Corrosion at the head-neck taper as a cause for adverse local tissue reactions after total hip arthroplasty. *J Bone Joint Surg Am* 2012;94:1655.
- [26] Jacobs JJ, Cooper HJ, Urban RM, Wixson RL, Della Valle CJ. What do we know about taper corrosion in total hip arthroplasty? *J Arthroplasty* 2014;29:668.
- [27] Lachiewicz PF, O'Dell JA. Trunnion corrosion in metal-on-polyethylene hip arthroplasty. *Bone Joint J* 2018;100-B:898.
- [28] Fokter SK, Rudolf R, Molicnik A. Titanium alloy femoral neck fracture—clinical and metallurgical analysis in 6 cases. *Acta Orthop* 2016;87:197.
- [29] Shah RR, Goldstein JM, Cipparrone NE, et al. Alarming high rate of implant fractures in one modular femoral stem design: a comparison of two implants. *J Arthroplasty* 2017;32:3157.
- [30] Gilbert JL, Buckley CA, Jacobs JJ. In vivo corrosion of modular hip prosthesis components in mixed and similar metal combinations. The effect of crevice, stress, motion, and alloy coupling. *J Biomed Mater Res* 1993;27:1533.