

IMAGES IN EMERGENCY MEDICINE

Cardiology

Twiddler's syndrome: The slow twist of a pruritic pacemaker

Fiona E. Gallahue MD | Amy Walker MD

The Department of Emergency Medicine, The University of Washington, Seattle, Washington, USA

Correspondence

Fiona E. Gallahue, MD, Associate Professor and Program Director, The Department of Emergency Medicine, The University of Washington, Seattle, WA 98104, USA.
 Email: fionagallahue@gmail.com

KEYWORDS

artificial, defibrillators, defibrillator complications, defibrillators implantable, pacemaker, twiddler syndrome

1 | CASE REPORT

A 77-year-old woman with history of cardiac arrest due to ventricular tachycardia, now 6 months status post implantable cardioverter defibrillator (ICD) placement, presented to the emergency department (ED) for 9 episodes of defibrillator firing at rest with ongoing shocks every 5–15 minutes. She denied chest pain not associated with the shocks, palpitations, or other symptoms before the ICD shocks. The patient noted recent generalized body itching including at the ICD site since pacemaker placement.

2 | DISCUSSION

There are 2 types of cardiac conduction devices, pacemakers to pace the heart, usually for symptomatic bradycardia, and ICDs to defibrillate patients to prevent cardiac arrest secondary to dysrhythmias. In the case of ICDs, the attached leads have 2 shock coils. One defibrillation coil is usually located in the region of the brachiocephalic vein–superior vena cava junction. The second is located in the right ventricle (RV). Pacemakers are more variable in the number of leads and location depending on the cause of the bradycardia. It may be helpful for the clinician to review prior chest imaging when reviewing current radiographs of patients with pacemakers or ICDs, especially if there is a concern for migration of their components.¹

In this patient, chest radiography after ICD placement showed parallel leads with appropriate placement, 1 shock coil located in the right atrium and 1 in the RV (Figure 1). However, an outpatient radiograph 4 months later demonstrated twisting by the pulse generator with




FIGURE 1 Immediately after ICD placement: Appropriately placed defibrillator leads: Black Narrow Arrow: Parallel ICD leads. Black Arrowhead: Right atrial appendage lead. Black Arrow: Right ventricular lead extending near the cardiac apex. ICD, implantable cardioverter defibrillator

the leads still appropriately placed (Figure 2). On the day of ED presentation, chest radiography revealed the RV lead was dislodged and migrated back to the RA. Both proximal defibrillator leads were twisted near the pulse generator (Figure 3).

This is an open access article under the terms of the [Creative Commons Attribution-NonCommercial-NoDerivs](https://creativecommons.org/licenses/by-nc-nd/4.0/) License, which permits use and distribution in any medium, provided the original work is properly cited, the use is non-commercial and no modifications or adaptations are made.

© 2020 The Authors. *JACEP Open* published by Wiley Periodicals LLC on behalf of the American College of Emergency Physicians.




FIGURE 2 Four months after placement: Appropriately placed defibrillator leads with proximal lead twist. Black Narrow Arrow: Note some proximal twisting of ICD leads, but the RV lead is still appropriately placed. Black Arrowhead: Right atrial appendage lead Black Arrow: Right ventricular lead extending near the cardiac apex. ICD, implantable cardioverter defibrillator; RV, right ventricle

The painless dislodgement of pacemaker leads from patient manipulation, itching in this case, is known as Twiddler's syndrome. Twiddler's syndrome was first described by Bayliss et al.² It usually occurs within the first year of implantation and is a potentially fatal complication. Patients may present with symptoms such as syncope, vertiginous disorders, fatigue, chest pain, rhythmic arm movements due to brachial plexus stimulation, or intermittent firing, as with this patient.³ The patient underwent successful lead revision with uneventful post-operative recovery. In this case, this patient demonstrated evidence of Twiddler's syndrome on an interim chest radiograph and may have benefited from counseling before her ED presentation.




FIGURE 3 Six months after placement: Compared to prior radiographs, the defibrillator electrodes have gradually migrated with right ventricular lead dislodgement. Black Narrow Arrow: Twisting of the proximal defibrillator leads near the pulse generator. Black Arrowhead: The right atrial appendage lead now appears to be located more superiorly near the junction of the superior vena cava and right atrium. Black Arrow: The right ventricular lead projects over the right atrium

REFERENCES

1. Aguilera AL, Volokhina YV, Fisher KL. Radiography of cardiac conduction devices: a comprehensive review. *Radiographics*. 2011;31(6):1669-1682.
2. Bayliss CE, Beanlands DS, Baird RJ. The Pacemaker-Twiddler's syndrome: a new complication of implantable transvenous pacemakers. *Can Med Assoc J*. 1968;99:371-373.
3. Tahirovic E, Haxhibeqiri-Karabdic I. Twiddler's syndrome: case report and literature review. *Heart Views*. 2018;19(1):27-31.

How to cite this article: Gallahue FE, Walker A. Twiddler's syndrome: The slow twist of a pruritic pacemaker. *JACEP Open*. 2020;1:674-675. <https://doi.org/10.1002/emp2.12148>