

CORRECTION

Correction: On the internal reaction forces, energy absorption, and fracture in the hip during simulated sideways fall impact

Ingmar Fleps, William S. Enns-Bray, Pierre Guy, Stephen J. Ferguson, Peter A. Cripton, Benedikt Helgason

In Fig 2, the markers PB1 and PB2 are incorrect. PB1 should be labeled LR1 and PB2 should be labeled LR2. Additionally, the marker d_{PB} should be removed. Please see the corrected Fig 2 here.



OPEN ACCESS

Citation: Fleps I, Enns-Bray WS, Guy P, Ferguson SJ, Cripton PA, Helgason B (2018) Correction: On the internal reaction forces, energy absorption, and fracture in the hip during simulated sideways fall impact. PLoS ONE 13(11): e0208286. https://doi.org/10.1371/journal.pone.0208286

Published: November 26, 2018

Copyright: © 2018 Fleps et al. This is an open access article distributed under the terms of the Creative Commons Attribution License, which permits unrestricted use, distribution, and reproduction in any medium, provided the original author and source are credited.






Fig 2. FEM of specimen H1391 aligned in initial position corresponding to the time of first contact with force plate during the experimental testing. Lower limb constructions coloured grey, lower limb masses coloured blue and soft tissue coloured orange. Marker points corresponding to location of video markers of the physical specimen are shown in black. Marker ST1 corresponds to a marker attached to the surrogate soft tissue above the right GT. Markers LR1 and LR2 correspond to the position of markers attached to the right and left side of the pelvic ring, respectively.

https://doi.org/10.1371/journal.pone.0208286.g001

Reference

 Fleps I, Enns-Bray WS, Guy P, Ferguson SJ, Cripton PA, Helgason B (2018) On the internal reaction forces, energy absorption, and fracture in the hip during simulated sideways fall impact. PLoS ONE 13 (8): e0200952. https://doi.org/10.1371/journal.pone.0200952 PMID: 30114192