IMAGES IN CARDIOVASCULAR INTERVENTION



Percutaneous removal of a knotted Swan–Ganz catheter

Hibiki Mima¹ · Soichiro Enomoto¹ · Yodo Tamaki¹ · Makoto Miyake¹ · Hirokazu Kondo¹ · Toshihiro Tamura¹

Received: 27 May 2021 / Accepted: 30 October 2021 / Published online: 8 November 2021 © The Author(s) 2021

A 48-year-old man who had undergone aortic valve surgery 1 week previously became hemodynamically unstable in the intensive care unit. His physician decided to insert a Swan–Ganz catheter (SGC) (Edwards Lifesciences, Tokyo, Japan) without fluoroscopic guidance. The SGC was inserted via the right internal jugular vein and advanced into the right ventricle, but it could not be advanced into the pulmonary artery. After repeated attempts, the physician pulled back the SGC, but it could not be retrieved. X-ray examination showed knot formation in the SGC, and the patient was referred to us.

First, a new 5-Fr sheath was placed in the right internal jugular vein, and a 0.014-inch guidewire (Cruise; Asahi Intecc, Tokyo, Japan) was passed through the center of the knot. A 6-mm balloon (Rx-Genity; Kaneka, Tokyo, Japan) was inflated to expand the knot diameter; however, the knot was not completely untied. A 10-mm-diameter Amplatz Goose Neck snare (Medtronic, Dublin, Ireland) was then advanced to the distal end of the SGC along with the Cruise wire. Finally, we grasped the tip of the SGC and pulled it back, causing untying of the knot and successful removal of the SGC.

Several interventional radiological strategies to remove knotted catheters have been reported, including dilating the knot by large-diameter balloons [1], covering the knot with a larger sheath, and pulling the catheter end back through the knot following balloon dilatation [2], which is the basis of our procedure and might be the most promising. However, this method has a possibility of creating another knot by passing the snare from the wrong side as shown in Fig. 1e2 and 4. Rotational angiography is required to check whether the snare is on the same side as the tip of the SGC, although the knot is likely to tilt to a preferred angle for the correct path (Fig. 1f). Sufficient knot dilation by adequately sized balloons is also important to avoid migrating the whole knotted catheter without untying. Surgical removal is required in some situations. If the knot is very large or multiple knots exist, pulling the catheter can cause vascular trauma. Furthermore, intracardiac structures may be injured if the knot is entrapped in the chordae tendineae or heart valves [3].

In conclusion, physicians should be aware of this rare complication and manipulate catheters carefully during blind procedures.

Soichiro Enomoto so_enomoto@yahoo.co.jp

¹ Department of Cardiology, Tenri Hospital, 200 Mishima-cho, Tenri, Nara 632-8552, Japan



Fig. 1 a Knot formation in the Swan–Ganz catheter. b Balloon dilatation loosened the knot. c The tip was pulled back by the snare passing through the knot. d1-4 Schematic diagram of the procedure. e1-4The snare must be on the same side as the tip of the Swan–Ganz cath-

Acknowledgements We thank Angela Morben, DVM, ELS, from Edanz (https://jp.edanz.com/ac) for editing a draft of this manuscript.

Open Access This article is licensed under a Creative Commons Attribution 4.0 International License, which permits use, sharing, adaptation, distribution and reproduction in any medium or format, as long as you give appropriate credit to the original author(s) and the source, provide a link to the Creative Commons licence, and indicate if changes were made. The images or other third party material in this article are included in the article's Creative Commons licence, unless indicated otherwise in a credit line to the material. If material is not included in the article's Creative Commons licence and your intended use is not permitted by statutory regulation or exceeds the permitted use, you will need to obtain permission directly from the copyright holder. To view a copy of this licence, visit http://creativecommons.org/licenses/by/4.0/.

References

 Matta A, Boudou N, Ohayon P, Carrié D. Angioplasty inflated balloon to unknot an entrapped Swan-Ganz catheter. Eur Heart J Case Rep. 2019;3:1–2. eter. **f** Rotational angiography showed whether the snare was on the correct path (red line) or not (blue line). Fortunately, the knot was tilted, which enabled the snare to follow the correct path easily

- Bhatti WA, Sinha S, Rowlands P. Percutaneous untying of a knot in a retained Swan-Ganz catheter. Cardiovasc Intervent Radiol. 2000;23:224–5.
- Karanikas ID, Polychronidis A, Vrachatis A, Arvanitis DP, Simopoulos CE, Lazarides MK. Removal of knotted intravascular devices Case report and review of the literature. Eur J Vasc Endovasc Surg. 2002;23:189–94.

Publisher's Note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.