

RESEARCH Open Access

In vitro corrosion of ZEK100 plates in Hank's Balanced Salt Solution

Hazibullah Waizy^{1*}, Andreas Weizbauer¹, Christian Modrejewski¹, Frank Witte¹, Henning Windhagen¹, Arne Lucas², Marc Kieke³, Berend Denkena², Peter Behrens³, Andrea Meyer-Lindenberg^{4,5}, Friedrich-Wilhelm Bach⁶ and Fritz Thorey^{1,7}

Abstract

Background: In recent years magnesium alloys have been intensively investigated as potential resorbable materials with appropriate mechanical and corrosion properties. Particularly in orthopedic research magnesium is interesting because of its mechanical properties close to those of natural bone, the prevention of both stress shielding and removal of the implant after surgery.

Methods: ZEK100 plates were examined in this in vitro study with Hank's Balanced Salt Solution under physiological conditions with a constant laminar flow rate. After 14, 28 and 42 days of immersion the ZEK100 plates were mechanically tested via four point bending test. The surfaces of the immersed specimens were characterized by SEM, EDX and XRD.

Results: The four point bending test displayed an increased bending strength after 6 weeks immersion compared to the 2 week group and 4 week group. The characterization of the surface revealed the presence of high amounts of O, P and Ca on the surface and small Mg content. This indicates the precipitation of calcium phosphates with low solubility on the surface of the ZEK100 plates.

Conclusions: The results of the present in vitro study indicate that ZEK100 is a potential candidate for degradable orthopedic implants. Further investigations are needed to examine the degradation behavior.

Keywords: Magnesium alloy, Corrosion, Plates, in vitro study

Background

The first published application of a plate for fracture fixation was 1886 by Carl Hansmann [1]. It was not until the beginning of the 20th century when plates as osteosynthesis systems was spread due to the works of William Arbuthnot Lane and Albin Lambotte. In 1907 Lane, a British surgeon, introduced perforated steel plates for use in internal fixation [2]. Lambotte was one of the first to apply pure magnesium plates in a clinical case to stabilize a fracture in a young man. After implantation he observed extensive subcutaneous gas cavities and local swelling caused by rapid degradation [3].

In recent years, new innovative magnesium alloys are being intensively investigated as potential resorbable materials with appropriate mechanical and corrosion properties. Particularly in orthopedic research magnesium is interesting because of its mechanical properties close to those of natural bone, the prevention of both stress shielding and



^{*} Correspondence: Hazibullah. Waizy@ddh-gruppe.de
¹Department of Orthopedic
Surgery, Hannover Medical School,
Anna-von-Borries-Str.1-7, 30625
Hannover, Germany
Full list of author information is
available at the end of the article

removal of the implant after surgery [4]. Orthopedic implants need to provide an initial fixation and a predictable, gradually degradation adapted to the bone healing process.

ZEK100 is a magnesium alloy which contains 1 wt% zinc, 0.1 wt% zirconium and 0.1 wt % rare earth metals [5]. Magnesium and its degradation products are non-toxic and it is an essential co-factor for many enzymes; especially for DNA replication and repair processes [6,7]. Furthermore, magnesium acts as a stabilizer of DNA and chromatin structure. The recommended daily dietary is approximately 300 mg for adults [6]. Zinc as an alloying ingredient contributes to strength due to solid solution strengthening [7]. In addition, zinc is one of the essential micro-nutrients in the human body with an estimated daily requirement of 15 mg. It is essential to structure and function of over 300 enzymatic reactions [8]. The zinc finger motif, which is determined by a single zinc ion in the base, is most frequently occurring in transcription factors [8]. Zirconium is usually used as a grain refinement agent in magnesium alloys without aluminum and thereby contributes to strengthening [7]. In an in vitro study with binary magnesium alloys an addition of Zn or Zr showed good cytocompatibility, improved strength and a reduced corrosion rate [9]. The rare earth metals comprise seventeen elements which can be classified into two groups: elements with high and limited solubility in magnesium [10]. Rare earth (RE) metals improve strength by solid solution strengthening and precipitation strengthening [7]. The in vitro test with Mg-Y indicate no significant cytotoxicity to osteoblasts; furthermore good cytocompatibility was observed with Mg-Zn-Y alloys [9,11]. Several RE containing alloys such as WE43 or LAE443 have been investigated in former studies and reported good biocompatibility in vivo [12-16].

The disadvantage of magnesium alloys is the production of hydrogen gas which accumulates in tissue cavities. The amount of gas production is dependent on the corrosion rate. The accumulation of gas of ZEK100 implants was found in the medullary cavity via μ -computed tomography (μ CT) examinations, though it did not became clinically visible [17].

In the present study, ZEK100 plates were examined in an in vitro model with Hank's Balanced Salt Solution under physiological conditions. A constant laminar flow of the corrosion medium was adjusted. The mechanical properties of the plates after corrosion were determined via four-point bending test. The surfaces of the immersed specimens were characterized by SEM, EDX and XRD.

Methods

Material

In this study plates for bone fixation of a biodegradable magnesium alloy were examined. The magnesium alloy ZEK100 contains 1 wt% zinc, 0.1 wt% zirconium and 0.1 wt% rare earth metals [5]. The analyzed chemical composition of the alloy by ICP-OES is given in Table 1. The ZEK100-specimens were cut into plates with dimensions of $50~\text{mm} \times 8~\text{mm} \times 1~\text{mm}$ by milling processes. In every plate five screw holes were

Table 1 Nominal and analyzed composition of the ZEK100 alloy

Element	Mg	Zn	Zr	Rare Earth Elements			
				Υ	Nd	Ce	La
Analyzed composition	98.53	0.961	0.211	0.146	0.02	0.092	0.042
Nominal composition	98.8	1	0.1	0.1			

drilled and counterbored. These screw holes have an inner diameter of 3 mm on the bone-side and a counterbore diameter of 5 mm (Figure 1).

Microstructural characterization

The corroded plates were analyzed by a scanning electron microscope (SEM) EVO 60 VP by Zeiss. Theses analyses also included an energy dispersive X-ray analysis (EDX) to detect the distribution of elements on the surface of the corroded specimens and on the cross-section area of the plates. Therefore the plates were cut in the section of the middle bore. To achieve an electro conductive surface for the SEM analysis the specimens were also sputtered with gold.

X-ray diffraction (XRD) investigations were performed with a STOE Theta-Theta diffractometer in reflection geometry (wavelength $\lambda = 1.54059$ Å). The 2θ range from 2 to 65° was scanned with a step size of 0.01° (3.0 s per step) using monochromatized Cu K α 1 radiation.

Immersion test in a system with a constant flow rate

The immersion test was carried out in Hanks' Balanced Salt Solution (HBSS) to simulate normal ion concentration under physiological tissue conditions. The chemical composition of HBSS is given in Table 2. The HBSS were produced as dry substance with phenol red by Biochrom AG, Berlin. The temperature in the test system was measured by a thermometer (Fisher Scientific, Schwerte, Germany) during corrosion every day and regulated to 37.4°C +/- 0.5°C . Also the pH was controlled every day during



Figure 1 Picture of a non-corroded plate. The plate consists of ZEK100 and has a dimension of 50 mm \times 8 mm \times 1 mm. In every plate five screw holes were drilled and counterbored with an inner diameter of 3 mm on the bone-side and a counterbore diameter of 5 mm.

Table 2 Chemical composition of Hanks' Balanced Salt Solutio	Table 2 Chemica	l composition	of Hanks'	Balanced	Salt Solution
--	-----------------	---------------	-----------	-----------------	---------------

Reagents	Concentration (mg/l)			
NaCl	8000			
KCI	400			
Na ₂ HPO ₄	48			
KH ₂ PO ₄	60			
$MgSO_4 \cdot 7H_20$	200			
CaCl ₂	140			
Glucose	1000			
Phenol red	10			
NaHCO ₃	350			

corrosion and remained at 7.4. Flow rate was regulated to 2.5 to 3.5 ml/min. After passing the ZEK100 alloys the solution was discarded (Figure 2).

In this study twelve ZEK100 plate demonstrators, divided into 3 groups with 4 demonstrators, were corroded and tested. The demonstrators were fixed into a test frame which allows a laminar flow of the HBSS. The first group was corroded over 14 days, the second group over 28 d and the third group over 42 days.

Mechanical testing

In order to specify the mechanical properties of the specimens, they were tested according to ISO 9585:1990. The four point bending test setup (Figure 3) was designed for tests with an uniaxial material-testing machine (Mini Bionix 858, MTS Systems in Mineapolis, USA). The test system consisted of four rollers with a diameter of 8 mm. The distance between the lower and outer rollers was 32 mm. 10 mm distance was




Figure 2 Picture of the in vitro corrosion testing setup. 1: Glass basin with Hank's Balanced Salt Solution. **2**: The corrosion medium was warmed in a water bath to 37.4 +/- 0.5°C. **3**: HBSS passes the test system with the specimens with a laminar flow rate of 2.5 to 3.5 ml/min Temperature is checked with a thermometer. The system is protected against heat loss with styrofoam. **4**: The flow rate was maintained with a pump. The solution was then discarded in a container.




Figure 3 Picture of the mechanical four-point bending test setup. The test system consisted of four rollers with a diameter of 8 mm. The distance between the lower and outer rollers was 32 mm. 10 mm distance was between the upper and inner rollers. The plates were positioned on the lower rollers according to the protocol of ISO 9585:1990.

between the upper and inner rollers. The plates were positioned on the lower rollers according to the protocol of ISO 9585:1990. The distance between the outer and inner rollers was 11 mm and contains a screw hole of the demonstrators. The test rig was produced by the Research Work Shop of the Medical School, Hannover, Germany.

Results

Microstructure and surface composition after immersion

The surface morphology of ZEK100 plates after exposure in Hank's Balanced Salt Solution are shown in the SEM images of Figures 4 and 5. On the corrosion surface cracks were found after all immersion intervals which might be caused by drying. At higher magnifications, some needle-shaped clusters appeared on the surface of the 2 weeks group and the 6 weeks group (Figure 4b, g). A more detailed picture of that structure is given in Figure 4h. In the SEM picture after 4 weeks immersion a peeling of corrosion surface can be observed in high magnification view. Small, agglomerated particles seemed to be formed on the surface (Figure 4e). The pictures of the cross-sections reveal local pits on the surface (Figure 5). More distinct and deep pits were found after 4 and 6 weeks immersion (Figure 5b, c).

EDX analyses were conducted on a small surface area after every corrosion interval to determine the elemental composition (Figure 6). The results revealed the presence of high amounts of the elements O, P and Ca and small amounts of C, Na, Mg, Cl and K (Table 3).




Figure 4 SEM pictures of the surface morphology of ZEK100 plates immersed in Hank's balanced salt solution. a)-c) after 2 weeks, d)-e) after 4 weeks, f)-h) after 6 weeks. The black arrow marks needle-shaped clusters.

X-ray diffraction (XRD) was applied to identify some of the corrosion products on the surface. Figure 7 presents the XRD patterns of the ZEK100 plates after all three different immersion intervals. In all spectra large magnesium and $Mg(OH)_2$ peaks are clearly visible.




Figure 5 SEM pictures of the cross-section area. a) 2 weeks, b) 4 weeks c) 6 weeks. The corrosion pits are marked by black arrows.

Mechanical characterization of the specimens after immersion

The bending strength was calculated from obtained load-deflection curves. The results are presented in Figure 8. The results of the bending test displayed a decrease of bending strength from immersion week 2 to immersion week 4. The tested plates after 6 weeks corrosion showed an increased bending strength.

Discussion

Fracture healing is a complex pathway with determine steps and the healing quality and speed depends on the size of the fracture gap and the achieved stability. Therefore an adjusted stability is essential for fracture healing. The discrepancy of the Young's





Figure 6 Example of the EDX analysis. The energy dispersive X-ray analysis (EDX) was applied in order to detect the distribution of elements on the surface of the corroded specimens.


Table 3 Results of the EDX analysis of the ZEK100 alloy

Element	2 weeks		4 weeks		6 weeks	
	wt%	at%	wt%	at%	wt%	at%
С	6.21	10.8	6.66	11.66	6.3	11.01
0	43.07	56.24	43.16	56.76	42.3	55.48
Na	0.63	0.57	0.6	0.55	1.94	1.77
Mg	10.88	9.35	7.7	6.67	10.36	8.94
P	16.94	11.43	15.34	10.42	14.99	10.16
Cl	0.08	0.05	0.16	0.09	0.06	0.04
K	0.28	0.15	0.34	0.19	0.6	0.32
Ca	21.92	11.42	26.03	13.66	23.45	12.28



modulus of the conventional implants (stainless steel or titan) in regard to bone promotes the occurrence of stress shielding with negative effects to the bone healing. Degradable implants from magnesium alloys are desirable because of the mentioned promising characteristics of magnesium. Standard tests with those implants according to ASTM protocols are rare.

In the present study, ZEK100 plates were examined in an in vitro model with Hank's Balanced Salt Solution under physiological conditions. The corrosion medium used in



this study is in its ionic content similar to blood plasma with a high chloride concentration. The degradation of magnesium and its alloys are described according to the following reactions [18]:

Anodic reaction: $Mg \rightarrow Mg^{2+} + 2e^{-}$ Cathodic reaction: $2 H_2O + 2e^{-} \rightarrow H_2\uparrow + 2 OH^{-}$

$$Mg^{2+} + 2 OH^{-} \rightarrow Mg(OH)_{2}(s)$$

It is reported that the protective Mg(OH)₂-film is formed rapidly after 2 h immersion [19]. The Mg(OH)₂-layer on the surface is dissolved by Cl⁻ into soluble MgCl₂:

$$Mg(OH)_2 \rightarrow MgCl_2 + 2 OH^-$$

An illustration of the reactions on the surface of the magnesium alloy is given in Figure 9. This diagram is in accordance with previous illustrations in Ref. [20,21] and is intended to demonstrate the corrosion processes on the surface. This dissolution reaction elevates the local hydroxide concentration near the surface. It is reported that in stagnant corrosion systems the degradation of magnesium and its alloys lead to an alkalization of the corrosive medium [22]. As a result of alkalization, a greater tendency for film formation is reported when the local pH value rise above 10.5 [23]. However, this effect might be minor in this study due to the NaHCO₃ buffer in the corrosion medium and the flow rate applied in this system. Nevertheless, it is reported that this buffering agent accelerates the dissolution of magnesium because of the consumption of the generated OH⁻ [24].

The corrosion in our model is most likely more influenced by the velocity. The accelerating corrosive effect of the flow rate obtains to (i) shear forces, (ii) the destruction or prevention of a protective surface layer and (iii) the prevention of micro-alkalization on the surface [7,23]. It is noticeable that a corrosion layer could be identified considering the flow rate adjusted in this immersion model. Wang et al. compared the degradation rate of a dynamic system with a flow rate to static conditions with Hank's Balanced Salt Solution by weight loss method [25]. An accelerated degradation rate was reported in this study under dynamic conditions; though the applied flow rate remains unclear [25].

The EDX analysis of our plates revealed a high amount of the elements Ca, P and O which indicates the precipitation of calcium phosphates with low solubility which was reported in previous studies [15,18,26]. The corrosion medium Hank's Balanced Salt Solution contains a certain amount of Ca^{2+} and PO_4^{3-} (Table 1). The most stable calcium phosphate is hydroxyapatite which forms according to the following reaction:

$$10 \text{ Ca}^{2+} + 6 \text{ PO}_4^{3-} + 2 \text{ OH}^- \rightarrow \text{Ca}_{10}(\text{PO}_4)_6(\text{OH})_2 [27].$$

Additional types of calcium phosphates are in order of increasing solubility: $Ca_2(PO_4)_3 \cdot nH2O$ (TCP), $Ca_8H_2(PO_4)_6 \cdot 5H2O$ (OCP) and $Ca(HPO_4) \cdot 5H_2O$ (DCPD) [27]. Hydroxyapatite is an essential component of the human bone and therefore the biocompatibility of this precipitation layer can be assumed. In addition, it has been shown that hydroxyapatite coated carboxymethyl chitosan (CMCS) enhances the proliferation and differentiation of osteoblasts and stem cells [28]. In a different study $Ca_3Mg_3(PO_4)_4$ was detected on the surface via XRD analysis of a Mg-Mn-Zn alloy immersed in




Figure 9 Schematic diagram of the reactions on the surface of the magnesium alloy. a) The galvanic reaction between magnesium and H_2O , b) the formation of the magnesium hydroxide film on the surface, c) the transformation of $Mg(OH)_2$ into soluble $MgCl_2$, d) the formation of hydroxyapatit on the surface due to consumption of Ca^{2+} and PO_4^{3-} .

Hank's solution [18]. The occurrence of this specific precipitation layer in our study is not supported by the low Mg content in our EDX analysis. The precipitation layers protect the magnesium alloy against aggressive ions in the corrosive medium and therefore reduce the corrosion rate [18]. In corrosive media containing HCO_3^- , which is the case in HBSS and blood plasma, the surface layer might consist of amorphous carbonated calcium phosphate with a schematic formula as follows: $(Mg, Ca)_x(PO_4)_y(CO_3)_z(OH)_i$ [29].

An advanced deposition of calcium and phosphate on the surface was determined by EDX analysis in all specimens. These results are comparable with Huan et al., who investigated an Mg-Zn-Zr alloy which is comparable to ZEK100 [30]. In this mentioned study the atomic content of Mg decreased slightly from 7 days immersion to 24 days while the atomic content of P and Ca increased [30]. The growth of the corrosion precipitation layer could not be detected in this study by EDX analysis after the different immersion time intervals. This let us assume that after 2 weeks the composition on the surface is stable which might be explained by an equilibrium between precipitation and erosion.

The effect of corrosion on the bending strength of plates with medical geometry has not been studied previously. In the present work a decreased bending strength of the plates was determined after 4 weeks in Hank's Balanced Salt Solution in comparison to the 2 week and 6 week group. It can be concluded that the change of the bending

strength after 4 week and 6 week immersion might be caused by the embrittlement of the magnesium alloy. As described hydrogen gas evolve as bubbles from the magnesium surface in consequence of dissolution. It is also reported that some hydrogen atoms enter the metal lattice [31,32]. This storage of hydrogen atoms results in hydrogen embrittlement of the magnesium alloy which degree is dependent on the immersion time [31]. It is reported that the cohesive strength of a magnesium alloy (AZ31) is reduced by hydrogen embrittlement [31].

In a previous in vivo study the bending stiffness of ZEK100-implants was determined via 3 point bending test. The maximum force (F_{max}) at the point of breakage of the explanted implants was decreased by 35% after 3 months and 60% after 6 months. These in vivo results differ from the results determined in this study. The geometry of the implant affects the determination of the mechanical properties of the specimen. In the in vivo study by Hühnerschulte et al. pins were used as implant geometry [17]. Further in vivo evaluations with the dimensions examined in this study would be helpful to improve the comparability between the in vivo and in vitro corrosion behavior. Different biomechanical results may be caused by different corrosion rates in vitro and in vivo [33,34]. It is reported that the in vitro corrosion rate is faster than in comparable in vivo studies [33]. Müller et al. reported that the corrosion rate was in vitro 1.7 times greater than in vivo for LAE442 [33]. Faster corrosion rates should be accompanied with an earlier loss of mechanical strength. A rapid decrease of the bending strength was determined from week 2 to week 4 in this in vitro study.

In contrast to this, in vivo μCT scans first demonstrate a decrease of the implant volume until week 4, thereupon an increased volume was determined up to week 8. After week 8 a continuously reduction of the volume was observed [17]. This increase of implant volume could be explained by the corrosion products on the surface which is not differentiated by the contour [17]. We assume that this increase of the volume caused by precipitation in the first weeks of corrosion affects the bending strength of the implants at that time. In our study the precipitation of calcium phosphates on the surface was observed via EDX analysis. This might explain the higher bending strength in week 6.

Primary bone healing is induced by a stiff construct and secondary bone healing by limited passive or active dynamization. However the role of mechanical stability in the fracture healing process is not totally cleared yet. Therefore it is not desirable to produce a total rigid complex. A mechanical stimulus is essential for bone growth and consolidation. It is still controversial which tactic would best improve the duration and strength of the healing fracture. But it is clear that stress shielding occurs as a result of the different Youngs moduls. The mention benefit of magnesium based implants is the low Youngs modul, this could avoid stress shielding.

There is a discrepancy between the maximum strength and the optimum strength. Magnesium plates are able to offer a time depending stability. However, it is important to define the demanded stability of a specific fracture. The needed stability of fracture depends on the bone quality, fracture geometry, localization of the fractured bone and the demand in rehabilitation. Therefore, the first demand should be define. According to the required implant characteristics the test standards should also be adjusted.

Conclusion

In the present work the degradation of ZEK100-plates was investigated. The bending strength increased after 6 weeks immersion compared to the 2 week group and 4 week group. The characterization of the surface revealed the presence of high amounts of O, P and Ca on the surface and small Mg content. This indicates the precipitation of calcium phosphates with low solubility on the surface of the ZEK100 plates. The present in vitro study indicates that ZEK100 is a potential candidate for degradable orthopedic implants. Further investigations are needed to examine the degradation behavior.

Abbreviations

EDX: Energy dispersive X-ray analysis; HBSS: Hank's Balanced Salt Solution; ICP-OES: Inductively coupled plasma optical emission spectrometry; μ CT: μ -computed tomography; RE: Rare earth; SEM: Scanning electron microscope; wt%: Weight percent; XRD: X-ray diffraction; ZEK100: Magnesium alloy with 98.8 wt% magnesium 1 wt% zinc, 0.1 wt% zirconium and 0.1 wt% rare earth metals

Acknowledgements

The authors gratefully acknowledge the financial support given by German research society (DFG) within the collaborative research project (SFB 599). We thank Markus Badenhop for excellent technical support. We thank Christopher Müller for the design of Figure 1 and Hendrik Wardenga for creating Figure 2.

Author details

¹Department of Orthopedic Surgery, Hannover Medical School, Anna-von-Borries-Str.1-7, 30625 Hannover, Germany. ²Institute of Production Engineering and Machine Tools (IFW), Leibnitz University of Hannover, Lise-Meitner-Str. 1, 30823 Garbsen, Germany. ³Institute for Inorganic Chemistry, Leibniz University of Hannover, Callinstr. 9, 30167 Hannover, Germany. ⁴Small Animal Clinic, School of Veterinary Medicine Hannover, Bischhofsholer Damm 15, 30173 Hannover, Germany. ⁵Clinic for Small Animal Surgery and Reproduction, Centre of Clinical Veterinary Medicine, Faculty of Veterinary Medicine Ludwig-Maximilians-Universität München, Veterinärstr. 13, 80539 Munich, Germany. ⁶Institute of Materials Science, Leibniz University Hannover, An der Universität 2, 30823 Garbsen, Germany. ⁷Center for Hip, Knee and Foot Surgery, ATOS Clinic Heidelberg, Bismarckstr. 9-15, 69115 Heidelberg, Germany.

Authors' contributions

HW supervised the in vitro corrosion examinations, analyzed the data and prepared the manuscript. AW analyzed the data and wrote the manuscript. CM performed the in vitro corrosion examinations and wrote the manuscript. FW and HW participated in the coordination of the corrosion experiments and helped to draft the manuscript. AL manufactured the plates and analyzed them via SEM and EDX. MK did the XRD analysis of the ZEK100 plates. BD, PB, AML and FWB revised the manuscript primarily although all authors made contributions. FT initiated the study, participated in its design and coordination. All authors read and approved the final manuscript.

Competing interests

The authors declare that they have no competing interests.

Received: 9 December 2011 Accepted: 13 March 2012 Published: 13 March 2012

References

- 1. Bartonicek J: Early history of operative treatment of fractures. Arch Orthop Trauma Surg 2010, 130:1385-1396.
- 2. Brand RA: Sir William Arbuthnot Lane, 1856-1943. Clin Orthop Relat Res 2009, 467:1939-1943.
- 3. Witte F: The history of biodegradable magnesium implants: a review. Acta Biomater 2010, 6:1680-1692.
- 4. Van Der Elst M, Patka P, van der Werken C: Biodegradable implants in fracture fixation: state of the art. *Unfallchirurg* 2000, 103:178-182.
- 5. Bach F-W, Rodman M, Rossberg A, Behrens B-A, Kurzare G: Macroscopic damage by the formation of shear bands during rolling and deep drawing of magnesium sheets. *J Min Met Mat Soc* 2005, **57**:57-61.
- 6. Hartwig A: Role of magnesium in genomic stability. Mutat Res 2001, 475:113-121.
- Witte F, Hort N, Vogt C, Cohen S, Kainer KU, Willumeit R, et al: Degradable biomaterials based on magnesium corrosion. Current Opinion in Solid State and Material Science 2008, 12:63-72.
- 8. Tapiero H, Tew KD: Trace elements in human physiology and pathology: zinc and metallothioneins. *Biomed Pharmacother* 2003. **57**:399-411.
- 9. Gu X, Zheng Y, Cheng Y, Zhong S, Xi T: In vitro corrosion and biocompatibility of binary magnesium alloys. *Biomaterials* 2009, **30**:484-498.
- 10. Feyerabend F, Fischer J, Holtz J, Witte F, Willumeit R, Drucker H, et al: Evaluation of short-term effects of rare earth and other elements used in magnesium alloys on primary cells and cell lines. Acta Biomater 2010, 6:1834-1842.
- Hanzi AC, Gerber I, Schinhammer M, Loffler JF, Uggowitzer PJ: On the in vitro and in vivo degradation performance and biological response of new biodegradable Mg-Y-Zn alloys. Acta Biomater 2010, 6:1824-1833.
- Castellani C, Lindtner RA, Hausbrandt P, Tschegg E, Stanzl-Tschegg SE, Zanoni G, et al: Bone-implant interface strength and osseointegration: Biodegradable magnesium alloy versus standard titanium control. Acta Biomater 2011, 7:432-440.

- 13. Reifenrath J, Krause A, Bormann D, von Rechenberg B, Windhagen H, Meyer-Lindenberg A: **Profound differences in the in-vivo-degradation and biocompatibility of two very similar rare-earth containing Mg-alloys in a rabbit model.**Mat -wiss u Werkstofftech 2010, 41:1054-1061.
- Thomann M, Krause C, Bormann D, von der Höh N, Windhagen H, Meyer-Lindenberg A: Comparision of the resorbable magnesium alloys LAE442 and MgCa0.8 concerning their mechanical properties, their progress of degradation and the bone-implant-contact after 12 months implantation duration in a rabbit model. Mat -wiss u Werkstofftech 2009, 40:82-87.
- 15. Witte F, Kaese V, Haferkamp H, Switzer E, Meyer-Lindenberg A, Wirth CJ, et al: In vivo corrosion of four magnesium alloys and the associated bone response. *Biomaterials* 2005, **26**:3557-3563.
- Witte F, Abeln I, Switzer E, Kaese V, Meyer-Lindenberg A, Windhagen H: Evaluation of the skin sensitizing potential of biodegradable magnesium alloys. J Biomed Mater Res A 2008, 86:1041-1047.
- Huehnerschulte TA, Angrisani N, Rittershaus D, Bormann D, Windhagen H, Meyer-Lindenberg A: In vivo corrosion of two novel magnesium alloys ZEK100 and AX30 and their mechanical suitability as biodegradable implants. Materials 2011. 4:1144-1167.
- 18. Yang L, Zhang E: Biocorrosion behavior of magnesium alloy in different simulated fluids for biomedical application. Mater Sci Eng C 2009, 29:1691-1696.
- Song Y, Shan D, Chen R, Zhang F, Han E-H: Biodegradable behaviors of AZ31 magnesium alloy in simulated body fluid. Mater Sci Eng C 2009, 29:1039-1045.
- 20. Li Z, Gu X, Lou S, Zheng Y: The development of binary Mg-Ca alloys for use as biodegradable materials within bone. *Biomaterials* 2008, **29**:1329-1344.
- 21. Zhang S, Li J, Song Y, Zhao C, Zhang X, Xie C, et al: In vitro degradation, hemolysis and MC3T3-E1 cell adhesion of biodegradable Mg-Zn alloy. Mater Sci Eng C 2009, 29:1907-1912.
- 22. Song G, Song S: A possible biodegradable magnesium implant material. Adv Eng Mater 2007, 9:298-302.
- 23. Song GL, Atrens A: Corrosion mechanisms of magnesium alloys. Adv Eng Mater 1999, 1:11-33.
- 24. Xin Y, Hu T, Chu PK: In vitro studies of biomedical magnesium alloys in a simulated physiological environment: a review. *Acta Biomater* 2011, **7**:1452-1459.
- 25. Wang H, Shi Z: In vitro biodegradation behavior of magnesium and magnesium alloy. *J Biomed Mater Res B Appl Biomater* 2011, **98B**:203-209.
- 26. Zhang S, Zhang X, Zhao C, Li J, Song Y, Xie C, et al: Research on an Mg-Zn alloy as a degradable biomaterial. Acta Biomater 2010, 6:626-640.
- Wang HX, Guan SK, Wang X, Ren CX, Wang LG: In vitro degradation and mechanical integrity of Mg-Zn-Ca alloy coated with Ca-deficient hydroxyapatite by the pulse electrodeposition process. Acta Biomater 2010, 6:1743-1748
- 28. Budiraharjo R, Neoh KG, Kang ET: Hydroxyapatite-coated carboxymethyl chitosan scaffolds for promoting osteoblast and stem cell differentiation. *J Colloid Interface Sci* 2011, **366**:224-232.
- Rettig R, Virtanen S: Composition of corrosion layers on a magnesium rare-earth alloy in simulated body fluids. J Biomed Mater Res A 2009, 88:359-369.
- Huan ZG, Leeflang MA, Zhou J, Fratila-Apachitei LE, Duszczyk J: In vitro degradation behavior and cytocompatibility of Mg-Zn-Zr alloys. J Mater Sci Mater Med 2010, 21:2623-2635.
- Song RG, Blawert C, Dietzel W, Atrens A: A study on stress corrosion cracking and hydrogen embrittlement of AZ31 magnesium alloy. Mater Sci Eng, A 2005, 399:308-317.
- 32. Zainal Abidin NI, Atrens AD, Martin D, Atrens A: Corrosion of high purity Mg, Mg2Zn0.2Mn, ZE41 and AZ91 in Hank's solution. Corros Sci 2011, 53:862-872.
- 33. Mueller W-D, Nascimento ML, de Mele MF: Critical discussion of the results from different corrosion studies of Mg and Mg alloys for biomaterial applications. *Acta Biomater* 2010, **6**:1749-1755.
- 34. Witte F, Fischer J, Nellesen J, Crostack HA, Kaese V, Pisch A, et al: In vitro and in vivo corrosion measurements of magnesium alloys. *Biomaterials* 2006, 27:1013-1018.

doi:10.1186/1475-925X-11-12

Cite this article as: Waizy et al.: In vitro corrosion of ZEK100 plates in Hank's Balanced Salt Solution. BioMedical Engineering OnLine 2012 11:12.

Submit your next manuscript to BioMed Central and take full advantage of:

- Convenient online submission
- Thorough peer review
- No space constraints or color figure charges
- Immediate publication on acceptance
- Inclusion in PubMed, CAS, Scopus and Google Scholar
- Research which is freely available for redistribution

Submit your manuscript at www.biomedcentral.com/submit

