



Since January 2020 Elsevier has created a COVID-19 resource centre with free information in English and Mandarin on the novel coronavirus COVID-19. The COVID-19 resource centre is hosted on Elsevier Connect, the company's public news and information website.

Elsevier hereby grants permission to make all its COVID-19-related research that is available on the COVID-19 resource centre - including this research content - immediately available in PubMed Central and other publicly funded repositories, such as the WHO COVID database with rights for unrestricted research re-use and analyses in any form or by any means with acknowledgement of the original source. These permissions are granted for free by Elsevier for as long as the COVID-19 resource centre remains active.



## Technical note

# The preventive effect of hydrocolloid dressing to prevent facial pressure and facial marks during use of medical protective equipment in the COVID-19 pandemic

J.L. Del Castillo Pardo de Vera <sup>a,\*</sup>, S. Reina Alcalde <sup>b</sup>,  
J.L. Cebrian Carretero <sup>a</sup>, M. Burgueño García <sup>a</sup>

<sup>a</sup> Oral and Maxillofacial Surgery Department, University Hospital La Paz, Madrid, Spain

<sup>b</sup> Intensive Care Unit, University Hospital Puerta de Hierro, Madrid, Spain

Accepted 30 April 2020

Available online 11 May 2020

**Keywords:** Covid-19; Hydrocolloid; facial injury

There seems to be no end in sight to the coronavirus crisis in Spain yet, and each day more people are becoming infected and are losing their lives due to the epidemic outbreak caused by the SARS-CoV-2 virus. Spain currently has the second-highest number of cases in the world after the United States.

All healthcare professionals should employ additional protective measures (masks, goggles, and special protective screens) to treat COVID-19 patients. The use of this equipment for long time periods can cause skin pressure discomfort and injuries, making it essential to take all available measures to protect the skin areas that may be affected and prevent this type of injury (Fig. 1). This is compounded by the fact that due to the high number of patients seen in hospitals, healthcare workers must work with these protection measures continuously in place for upwards of 4–5 hours on a daily basis, especially in the case of nursing staff.

Hydrocolloid is semi-permeable material that is present as a layer within a film or foam pad which adheres to the skin, usually used for wound healing. A hydrocolloid dressing (Comfeel<sup>®</sup>Plus; Coloplast) is used for this purpose.



Fig. 1. A distinctive red line can be seen on this nurse's forehead from where her protective equipment pressed down on her face, and an erythematous zone in the nasal dorsum.

After the hydrocolloid dressing has been trimmed the adhesive dressing is then placed over the skin of the nasal dorsum, cheeks and forehead, covering the area where the mask and protective glasses will rest (Figs. 2 and 3).

A particularly damaged and painful location despite daily use of the strips of for the masks and the elastic band straps of protective glasses and screens with cranial support are the areas of the root of the auricular helix. We will also apply

\* Corresponding author at: Oral and Maxillofacial Surgery Department, University Hospital La Paz, Pº Castellana 261, 28046 Madrid, Spain. Tel.: +0034917277000.

E-mail addresses: [jldelcastillopardo@gmail.com](mailto:jldelcastillopardo@gmail.com)

(J.L. Del Castillo Pardo de Vera), [kony74@hotmail.com](mailto:kony74@hotmail.com)

(S. Reina Alcalde), [rodrigator2001@hotmail.com](mailto:rodrigator2001@hotmail.com) (J.L. Cebrian Carretero), [mburgueno@me.com](mailto:mburgueno@me.com) (M. Burgueño García).



Fig. 2. This nurse has hydrocolloid on her cheeks as well as her forehead to stop her protective outfit from rubbing and causing pain.



Fig. 3. The protective equipment adapts perfectly to the facial surface and the skin on which both the mask and glasses rest. It is completely protected.

a hydrocolloid dressing to measure friction in these areas (Fig. 4).

Most publications related to the prevention of facial injuries caused by medical equipment are described in patients but not amongst healthcare professionals.<sup>1–3</sup> The medical devices that most often cause skin lesions at facial level are ventilation masks, nasogastric tubes, and orotracheal tubes alongside their securing tapes.



Fig. 4. The areas of the root of the auricular helix must especially be covered by the hydrocolloid to avoid skin injury.

The use of face masks and goggles for hours on end in this COVID-19 pandemic situation results in greater sweating which is aggravated by the large number of patients being treated and the stressful situation of possible contagion.

Severe acute respiratory syndrome (SARS) was first officially reported in Asia in February 2003.<sup>4</sup> Personal protective equipment such as the N95 mask, gloves, and gowns would be worn often for hours at a time. The most common adverse reaction reported to the N95 mask was acne; some healthcare professionals suffered from the pressure-related effects of mask use, mainly in the form of a rash or sores over the nasal bridge. Previous studies have shown the incidence of nasal bridge pressure ulcers during the use of acute Non-invasive ventilation to be between 5%–20%.<sup>5</sup>

## Conclusion

We recommend the use of hydrocolloid sheets cut to the size and shape of each health professional to avoid continuous chafing in the areas surrounding the mask and protective glasses at the level of the nasal dorsum, forehead and cheeks during the COVID-19 crisis.

**Ethics statement/confirmation of patients' permission**

Ethics approval is not required. Patients' permission not applicable

**Conflict of interest**

We have no conflicts of interest.

**References**

1. Schwartz D, Magen YK, Levy A, et al. Effects of humidity on skin friction against medical textiles as related to prevention of pressure injuries. *Int Wound J* 2018;1–9.
2. Schallom M, Cracchiolo L, Falker A, et al. Pressure ulcer incidence in patients wearing nasal-oral versus fullface noninvasive ventilation masks. *Am J Crit Care* 2015;24:349–56.
3. Lew TWK, Kwek TK, Tai D, et al. Acute respiratory distress syndrome in critically ill patients with SARS. *JAMA* 2003;290:374–80.
4. Foo CC, Goon AT, Leow YH, et al. Adverse skin reactions to personal protective equipment against acute respiratory syndrome—a descriptive study in Singapore. *Contact Dermatitis* 2006;55:291–4.
5. Yamaguti WP, Moderno EV, Yamashita SY, et al. Treatment-related risk factors for development of skin breakdown in subjects with acute respiratory failure undergoing non-invasive ventilation or CPAP. *Respir Care* 2014;59:1530–6.